










This section left blank intentionally.






















		SIZE 65-40-250S	RPM 3500	IMP.REF SS	CURVE No. 26402
--	--	---------------------------	--------------------	----------------------	---------------------------

This section left blank intentionally.








		SIZE 80-65-125S	RPM 3500	IMP.REF SS	CURVE No. 26103
--	--	---------------------------	--------------------	----------------------	---------------------------




		SIZE 80-65-125S	RPM 1750	IMP.REF SS	CURVE No. 46103
--	--	---------------------------	--------------------	----------------------	---------------------------







SIZE	RPM	IMP.REF	CURVE No.
80-50-200S	3500	SS	26303





SIZE	RPM	IMP.REF	CURVE No.
80-50-200S	1750	SS	46303




		SIZE 80-50-250S	RPM 3500	IMP.REF SS	CURVE No. 26403
--	--	---------------------------	--------------------	----------------------	---------------------------




		SIZE 80-50-250S	RPM 1750	IMP.REF SS	CURVE No. 46403
--	--	---------------------------	--------------------	----------------------	---------------------------











		SIZE 100-80-125S	RPM 3500	IMP.REF SS	CURVE No. 26104
--	--	----------------------------	--------------------	----------------------	---------------------------




		SIZE 100-80-125S	RPM 1750	IMP.REF SS	CURVE No. 46104
--	--	----------------------------	--------------------	----------------------	---------------------------
















		SIZE 100-65-315S	RPM 3500	IMP.REF SS	CURVE No. 26503
--	--	----------------------------	--------------------	----------------------	---------------------------




		SIZE 100-65-315S	RPM 1750	IMP.REF SS	CURVE No. 46503
--	--	----------------------------	--------------------	----------------------	---------------------------









This section left blank intentionally.







		SIZE 125-100-200S	RPM 3500	IMP.REF SS	CURVE No. 26306
--	--	-----------------------------	--------------------	----------------------	---------------------------





		SIZE 125-100-200S	RPM 1750	IMP.REF SS	CURVE No. 46306
--	--	-----------------------------	--------------------	----------------------	---------------------------




		SIZE 125-100-250S	RPM 3500	IMP.REF SS	CURVE No. 26406
--	--	-----------------------------	--------------------	----------------------	---------------------------




		SIZE 125-100-250S	RPM 1750	IMP.REF SS	CURVE No. 46406
--	--	-----------------------------	--------------------	----------------------	---------------------------









		SIZE 125-100-400S	RPM 1750	IMP.REF SS	CURVE No. 46602
--	--	-----------------------------	--------------------	----------------------	---------------------------



		SIZE 150-125-250S	RPM 1750	IMP.REF SS	CURVE No. 46407
--	--	-----------------------------	--------------------	----------------------	---------------------------





THIS PAGE LEFT BLANK INTENTIONALLY